

DACW66-02-B-0027, Madison-Marianna Bridges Scour Repairs			
Quantities Last Updated: (Amendments- None)		8/13/02 8:39 AM	
Item	Quantity Calculations Description For Lump Sum Items	Estimated Quantity	U/M
2	Clearing	1	LS
2a	Clearing Total ROW	36.0	AC
2b	Clearing Top Bank to ROW	10.5	AC
7	Rough Dressing, Fertilizing and Seeding	1	LS
7a	Rough Dressing, Fertilizing and Seeding	10.5	AC
<p>It is to be expressly understood that the accuracy of these estimates is in no way warranted and that the furnishing of this information to a bidder will not relieve him of his responsibility to estimate the quantities involved. It is further to be expressly understood that in no case will such estimate be used as a basis of claim against the Government.</p>			
<p>If you have any questions about these quantities, please contact Neal E. Newman at neal.e.newman@mvm02.usace.army.mil, 901-544-0890 (Work), or 901-544-4924 (Fax).</p>			